

## WEEKLY SUMMARY REPORT

---

Client:	Needham DPW	Dates:	12/23/2019 to 12/27/2019
Contract:	Rosemary Lake Dredging		
Contractor:	Maverick Construction Co., Inc.	Inspector(s) on site:	Caroline Armstrong

---

### WORK COMPLETED THIS WEEK

---

- Weekly turbidity monitoring conducted on Tuesday and Friday along Rosemary Brook.
- On-going equipment and material mobilization.
- Evaluation of analytical data from lake sediment sampling.

### WORK ANTICIPATED FOR NEXT WEEK

---

- Weekly turbidity monitoring to be conducted along Rosemary Brook.
- Continue construction of access ramp into Lake. On-going construction of staging area.
- Mobilization of excavators.
- Test pitting for Town water pipe location (Pending, date to be determined).
- Maverick to begin working on filtration system.
- On-going equipment procurement and installation.

## PHOTOS

---



Tuesday (12/24/2019)



Friday (12/27/2019)

**Lake bed with staging area in background**



Tuesday (12/24/2019)



Friday (12/27/2019)

**Lake bed**





Tuesday (12/24/2019)



Friday (12/27/2019)

### Lake Outfall





Tuesday (12/24/2019)



Friday (12/27/2019)

**Station 1 (Petrini Property) – Turbidity and sediment depth readings taken on Tuesday and Friday.**



Tuesday (12/24/2019)



Friday (12/27/2019)

**Station 1 (Petrini Property) – Turbidity and sediment depth readings taken on Tuesday and Friday.**





Tuesday (12/24/2019)



Friday (12/27/2019)

**Station 2 (West Street) – Turbidity and sediment depth readings taken on Tuesday and Friday.**



Tuesday (12/24/2019)



Friday (12/27/2019)

**Station 2 (West Street) – Turbidity and sediment depth readings taken on Tuesday and Friday.**